

Operator: EXTRACTION OIL & GAS INC

Location Name: MERLIN PAD

Loc ID: 456260

Inspection: 679605603



Exhibit A

CA: Bucket near condensate tank. Comply with Rule 606.

CA Resolution: Bucket left on top of condensate tank has been removed to comply with Rule 606.



Exhibit A



Exhibit B



Exhibit C

CA: Unused equipment near temporary tank and compressor. Comply with Rule 606.

CA Resolution: Unused equipment identified at various areas of the location have been removed to comply with Rule 606.

CA: Appears temporary tank is not grounded. Design all equipment to prevent accumulation of static charge per Rule 608.d.

CA Resolution: Operator has addressed and corrected issue to ground temporary tank, and is now in compliance with Rule 608.d