

Final Reclamation and Stormwater Inspection

Date: 05/15/2023

Operator: PADCO LLC - 24500

Location ID: 317036

Inspection Document #: 708200246

Washington County, CO

SENE Section 32 T2N R53W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Fassler #3
Location ID: 317036



Photo 1. Facing south towards the former well. It does not appear the access road has been reclaimed with the presence of asphalt/road base material, contouring/grading that does not reflect adjacent reference areas, and non-uniform vegetation cover.

Inspection Photos
Location Name: Fassler #3
Location ID: 317036



Photo 2. Facing south at location. It does not appear the location is progressing towards Rule 1004 reclamation standards with the presence of undesirable vegetation (e.g. russian thistle) and areas of non-uniform vegetation cover resulting in bare soil. The former well location is not reflective of reference areas.

Inspection Photos
Location Name: Fassler #3
Location ID: 317036



Photo 3. Close up of russian thistle observed on location. This undesirable weed species will need to be managed for in the future.

Inspection Photos
Location Name: Fassler #3
Location ID: 317036



Photo 4. Facing northwest from the southern portion of the location; see comments in Photo 2.

Inspection Photos
Location Name: Fassler #3
Location ID: 317036



Photo 5. Reference are photo taken west of location, facing west.