

# Final Reclamation and Stormwater Inspection

Date: 05/15/2023

Operator: PADCO LLC - 24500

Location ID: 317035

Inspection Document #: 708200247

Washington County, CO

SWNW Section 33 T2N R53W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: United States Colorado 2-A  
Location ID: 317035



**Photo 1.** It does not appear the access road has been reclaimed with the presence of road base material and evidence that the road has not been contoured/graded to reflect adjacent areas (e.g. cut slopes pictured in next photos).



Inspection Photos  
Location Name: United States Colorado 2-A  
Location ID: 317035



**Photo 2.** See comments in Photo 1.



Inspection Photos  
Location Name: United States Colorado 2-A  
Location ID: 317035



**Photo 3.** Close up of road base material on access road; see comments in Photo 1.



Inspection Photos  
Location Name: United States Colorado 2-A  
Location ID: 317035



**Photo 4.** Facing east at the PA well. Reclaimed areas are not progressing towards Rule 1004 standards with evidence of non-uniform vegetative cover resulting in areas of bare soil.



Inspection Photos  
Location Name: United States Colorado 2-A  
Location ID: 317035



**Photo 5.** Facing east at the former production area/pits. Photo illustrates almost uniform cover of Colorado List C Noxious weed (e.g. cheat grass). The operator will need to control/manage this infestation before it begins to spread onto adjacent rangeland, where cheatgrass was not detected.





**Photo 6.** Close up photo of cheatgrass observed within the reclaimed areas.



Inspection Photos  
Location Name: United States Colorado 2-A  
Location ID: 317035



**Photo 7.** Undesirable vegetation (e.g. russian thistle) observed within the former pit location.



Inspection Photos  
Location Name: United States Colorado 2-A  
Location ID: 317035



**Photo 8.** Access road will need to be reclaimed, including but not limited to, removing road base, decompacting, and contouring/grading to reflect adjacent topography/areas.