

Inspection Photos

API: 061-06743

Operator: WESTERN OPERATING COMPANY

Inspection Date: 5/15/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06743 | Date: 5/15/2023

Inspection Photos



Photo 1. Facing north toward the access road. It appears soil has been hauled in and decompacted but it does not appear that seeding has been completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06743 | Date: 5/15/2023

Inspection Photos



Photo 2. Facing north toward the location. Seeding and stabilization of soils has not been completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06743 | Date: 5/15/2023

Inspection Photos



Photo 3. There are 3 wires sticking out of the ground at center of location that need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06743 | Date: 5/15/2023