

# Inspection Photos

API: 061-05143

Operator: WESTERN OPERATING COMPANY

Inspection Date: 5/15/2023



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05143 | Date: 5/15/2023

## Inspection Photos



**Photo 1.** Facing toward the tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05143 | Date: 5/15/2023

## Inspection Photos



**Photo 2.** Facing southwest toward the area north of the tank battery where historic spilled occurred and is under remediation. Soils in this area have recently been seeded and straw mulched.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-05143 | Date: 5/15/2023



## Inspection Photos



**Photo 4.** Facing northwest toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05143 | Date: 5/15/2023

## Inspection Photos



**Photo 5.** There is oily material being stored in this containment which needs to be removed and properly disposed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05143 | Date: 5/15/2023