

Inspection Photos

5/15/2023

Operator: LARAMIE ENERGY LLC #10433

Location Number: 334552

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 334552



May 15, 2023



May 15, 2023

Photo 1: Location overview

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location Number: 334552



Photo 2: Photos 2-4 examples showing secondary containment BMP at the tank battery is not longer impervious to contain a spill or release. Liner material appears to have exceeded life expectancy and is showing signs of degradation throughout the BMP, including areas where holes/tears are not yet apparent.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 334552



Photo 3: See comments under photo 2.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location Number: 334552



Photo 5: See comments under photo 2.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 334552



Photo 5: Photos 5-6 examples showing liner material, and a concrete block observed on the north end of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 334552



Photo 6: See comments under photo 5.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 334552



Photo 7: Wells on Location.

