

Inspection Photos
Location Name: Edwards 43-9
Location ID: 331536




Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos
Location Name: Edwards 43-9
Location ID: 331536



Colorado Oil & Gas Conservation Commission
 40.41189, -104.88904, 1500.9m, 262°
 May 15, 2023 10:12:39

Photo 3: Debris inside tank battery (NW)



Colorado Oil & Gas Conservation Commission
 40.41211, -104.88906, 1498.1m, 313°
 May 15, 2023 10:11:00

Photo 4: Gas meter is not annually calibrated

Inspection Photos
Location Name: Edwards 43-9
Location ID: 331536




Photo 5: Debris



Photo 6: Debris

Inspection Photos
Location Name: Edwards 43-9
Location ID: 331536



Photo 7: Wellhead Sign



Photo 8: Wellhead; weeds