

Inspection Photos
Location Name: NHF-65N63W/9NWSW
Location #: 331573



Photo #1
NHF 13-9 (123-20921) Wellsite
Temporarily Abandoned | TA



Photo #2
NHF 13-9, 24-9 Battery site
Inactive | Shut-down

Inspection Photos
Location Name: NHF-65N63W/9NWSW
Location #: 331573



Photo #3
NHF 13-9, 24-9 Battery site
Inactive | Shut-down
Tank(s): SE corner



Photo #4
NHF 13-9, 24-9 Battery site
Inactive | Shut-down
ECD(s), Separator(s)

Inspection Photos
Location Name: NHF-65N63W/9NWSW
Location #: 331573



Photo #5
NHF 13-9, 24-9 Battery site
Inactive | Shut-down
Battery sign(s)