

Inspection Photos
Location Name: NHF-65N63W/9SESW
Location #: 331575



Photo #1
NHF 24-9 (123-20923) Wellsite
Temporarily Abandoned | TA



Photo #2
NHF 13-9, 24-9 Battery site
Inactive | Shut-down
Equipment documented: Loc. # 331573