

Inspection Photos

API: 061-06392

Operator: CHEMCO INC

Inspection Date: 5/15/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06392 - Date: 5/15/2023

Inspection Photos



Photo 1. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06392 - Date: 5/15/2023

Inspection Photos



Photo 2. There are oil stained soils at the base of the pumpjack that need to be cleaned up. There is no secondary containment of the chemical barrel.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06392 - Date: 5/15/2023

Inspection Photos



Photo 3. East side of the location. There is a tire, cement block, and metal bar that need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06392 - Date: 5/15/2023

Inspection Photos



Photo 4. The fence around the tank battery is not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06392 - Date: 5/15/2023