

# Inspection Photos

Fac ID: 482453

Operator: CHEMCO INC

Inspection Date: 5/15/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Fac ID: 482453  
- Date: 5/15/2023

## Inspection Photos



**Photo 1.** Facing toward the offsite tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Fac ID: 482453 - Date: 5/15/2023

## Inspection Photos



**Photo 2.** There is oil stained soils at the tank outlet that need to be cleaned up. The containment cover needs to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Fac ID: 482453 - Date: 5/15/2023