

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SE14W

Location #324092



SW Corner of Location – Photo #03468



SE Corner of Location – Photo #03469

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location #324092



Wellhead – Photo #03465

Separator – Photo #03471

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location #324092



Separator – Photo #03470



Tank Battery – Photo #03472

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location #324092



Open-Ended Load Line – Photo #03474



Location Lacks Stabilization – Photo #03476

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location #324092



Access Road Degradation/Transportation of Sediment – Photo #03478



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03479