

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 32-23 Pad

Location ID: 426123



Photo # 7991 From entrance to location



Photo # 7992 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 32-23 Pad

Location ID: 426123



Photo # 7993 Location



Photo # 7994 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 32-23 Pad

Location ID: 426123



Photo # 5718 From Inspection 708900306 conducted on 04/19/2023 Meter calibration info not conspicuously posted



Photo # 7999 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 32-23 Pad

Location ID: 426123



Photo # 5719 From Inspection 708900306 conducted on 04/19/2023 Meter calibration info not conspicuously posted



Photo # 7997 Meter calibration info not conspicuously posted