

TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/2NENE

Location #324024



NW Corner of Location – Photo #03430



SW Corner of Location – Photo #03431

TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/2NENE

Location #324024



SE Corner of Location – Photo #03432



NE Corner of Location – Photo #03433

TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/2NENE

Location #324024



Wellhead – Photo #03434



Separator – Photo #03437

TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/2NENE

Location #324024



Location Lacks Stabilization – Photo #03438



Location Lacks Stabilization – Photo #03439

TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/2NENE

Location #324024



Lease Road Lacks Stabilization – Photo #03429



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03441