

Inspection Photos
Location Name: Garden Creek 12-19H
Location ID: 421221



Photo 1 – Tank Battery

Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Garden Creek 12-19H
Location ID: 421221



Photo 3 – Heater Treater



Photo 4 – Gas Meter

Inspection Photos
Location Name: Garden Creek 12-19H
Location ID: 421221



Photo 5 – ECD – Flare has been removed

Photo 6 – Pumping Unit

Inspection Photos
Location Name: Garden Creek 12-19H
Location ID: 421221



Photo 7 – Wellhead




Photo 8 – 1” Riser Unmarked

Inspection Photos
Location Name: Garden Creek 12-19H
Location ID: 421221



Photo 9 – SW Deadman