

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number: 403209911 Date Received: 10/27/2022

EARTHEN PIT REPORT / PERMIT

This form is to be used for both reporting and permitting pits. Rule 908 describes when a Permit with prior approval, or a Report within 30 days is required for pits. Submit required attachments and forms.

Form Type: [ ] PERMIT [X] REPORT OGCC PIT NUMBER: 116566

NOTE: Operator to provide OGCC Pit Number only if available on an existing pit for pit report

OGCC Operator Number: 95960 Contact Name: April Stegall
Name of Operator: WEXPRO COMPANY
Address: P O BOX 45003 Phone: (307) 352-7561
City: SALT LAKE CITY State: UT Zip: 84145-0601 Email: april.stegall@dominionenergy.com

Pit Location Information

Operator's Pit/Facility Name: SOUTH POWDER WASH FIELD COMP. Operator's Pit/Facility Number:
API Number (associated well): 05- 081 00
OGCC Location ID (associated location): Or Form 2A #
Pit Location (QtrQtr, Sec, Twp, Rng, Meridian): SWSE-4-11N-97W-6
Latitude: Longitude: County: MOFFAT

Operation Information

Construction Date: 05/21/1979 Actual or Planned: Planned Pit Type: Unlined
Per rule 405.c: Operators will provide the Commission written notice 2 business days in advance of a Pit liner installation at any facility.
Pit Use/Type (Check all that apply):
[X] Production: [ ] Skimming/Settling [X] Produced Water Storage [ ] Percolation [ ] Evaporation
[ ] Special Purpose: [ ] Flare [ ] Blowdown [ ] BS&W/Tank Bottoms
[ ] Multi-Well Pit: [ ] Check if Rule 909.g.(1-4) applies.
[ ] Cuttings Trench
[ ] Form 15 Exception Pit Submitted within 30 Days after Constructing (908.c): [ ] Emergency [ ] Workover [ ] Plugging
Method of treatment prior to discharge into pit: separation
Offsite disposal of [ ] Injection; [X] Commercial; [ ] Reuse/Recycle; [ ] NPDES; Permit Number:
Other Information:
Actual construction date is unknown. Original pit permit shows it was approved on 5/21/79. This pit has been removed from service and may have been backfilled. This form is being submitted to change the status to inactive while Wexpro Company gathers closure documentation.

Site Conditions

Enter 5280 for distance greater than 1 mile.
Distance (in feet) to the nearest surface water: 951 Ground Water (depth): 50 Water Well: 2061
Distance (in feet) to nearest Building Unit: 5280
Distance (in feet) to nearest Designated Outside Activity Area: 5280

**Pit Design and Construction**

Size of Pit (in feet): Length: 10 Width: 10 Depth: 10 Calculated Working Volume (in barrels): 180  
Flow Rates (in bbl/day): Inflow: 0 Outflow: 0 Evaporation: 0 Percolation: 0  
Primary Liner. Type: None Thickness (mil): 0  
Operational Lifespan, per manufacturer's specs (years): 0  
Secondary Liner (if present): Type: None Thickness (mil): 0  
Operational Lifespan, per manufacturer's specs (years): 0  
Is Pit Fenced? No Is Pit Netted? No Leak Detection? No

**Pit Emissions**

Attach Pit Emission Calculations.

Estimated tons per year (tpy) of volatile organic compounds (VOCs): 0 (Round to nearest whole ton.)

Other Information:

Actual size of the pit is unknown and was gathered from permit data. This pit was previously removed from service and this form is being submitted to change the status to inactive while Wexpro Company gathers closure documentation.

Operator Comments: This pit was previously removed from service and this form is being submitted to change the status to inactive while Wexpro Company gathers closure documentation.

**Certification**

Rule 909.e.(3): If an Operator allows oil or condensate (free product or sheen) to accumulate in a Pit, then the Director may revoke the Operator's Form 15 and require the Operator to close and remediate the Pit.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: April Stegall  
Title: Reclamation Agent Email: april.stegall@dominionenergy.com Date: 10/27/2022

**Approval**

Signed:  Title: Director of COGCC Date: 05/18/2023

## Best Management Practices

<u>No</u>	<u>BMP/COA Type</u>	<u>Description</u>
1	Interim Reclamation	This pit was removed from service and this form is being submitted to change the status to inactive while Wexpro Company gathers closure documentation.

Total: 1 comment(s)

### CONDITIONS OF APPROVAL:

<u>COA Type</u>	<u>Description</u>
0 COA	

## Attachment List

<u>Att Doc Num</u>	<u>Name</u>
403209911	PIT REPORT SUBMITTED
403209940	SENSITIVE AREA DETERMINATION

Total Attach: 2 Files

## General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	COGCC has only active or closed status on Pits. The operator may yet receive a letter from the COGCC requesting an update on this pit (909.j), that report is generated by the database, please consider approval of this report as compliance. There is a Remediation Project for this pit REM # 10145.	03/29/2023

Total: 1 comment(s)