

Interim Reclamation and Stormwater Inspection

Date: 05/15/2023

Operator: PADCO LLC - 24500

Location ID: 317233

Inspection Document #: 708200244

Washington County, CO

NENE Section 32 T2N R53W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fassler 6
Location ID: 317233



Photo 1. Interim reclamation areas appear reflective of the reference areas at the time of this inspection. Guy line anchors do not appear to be properly marked.

Inspection Photos
Location Name: Fassler 6
Location ID: 317233



Photo 2. See comments in Photo 1.

Inspection Photos
Location Name: Fassler 6
Location ID: 317233




Photo 3. See comments in Photo 1.

Inspection Photos
Location Name: Fassler 6
Location ID: 317233



Photo 4. See comments in Photo 1.



Photo 5. Day tanks at wellhead do not appear to have any wildlife exclusion devices installed.