

# Inspection Photos

May 16, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 383131

Location Name: BJM DISPOSAL-67S92W/6NESE

Inspection Document #: 702801518

Garfield County, CO

NESE Section 6 T7S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: BJM DISPOSAL-67S92W/6NESE

Location ID: 383131



**Photo 1.** Photo taken from the east shows the reclaimed access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801518

Inspection Photos

Location Name: BJM DISPOSAL-67S92W/6NESE

Location ID: 383131



**Photo 2.** Photo taken from the northwest shows an overview of the northern portion of the location. Weedy areas are circled.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801518

Inspection Photos

Location Name: BJM DISPOSAL-67S92W/6NESE

Location ID: 383131



**Photo 3.** Photo shows an overview of the weedy northern portion of the location circled in Photo 2.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801518

Inspection Photos

Location Name: BJM DISPOSAL-67S92W/6NESE

Location ID: 383131



**Photo 4.** Photo taken from the northwest shows an overview of the southern portion of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801518

## Inspection Photos

Location Name: BJM DISPOSAL-67S92W/6NESE

Location ID: 383131



**Photo 5.** Photo taken from the northeast of the Location shows the start of disturbed area vegetation monitoring transect #1.



**Photo 6.** Photo taken from the southwest of the Location shows the start of disturbed area vegetation monitoring transect #2.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801518

Inspection Photos

Location Name: BJM DISPOSAL-67S92W/6NESE

Location ID: 383131



**Photo 7.** Photos taken to the northeast of the location shows the start (left) and end (right) of the reference area vegetation monitoring transect.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801518