

# Inspection Photos

May 16, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 324054

Location Name: MAMM CREEK RANCH-67S92W/20NWSW

Inspection Document #: 702801523

Garfield County, CO

NWSW Section 20 T7S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: MAMM CREEK RANCH-67S92W/20NWSW

Location ID: 324054



**Photo 1.** Photos show the access road from the north (left) and location entrance/south (right).



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Number: 702801523

Inspection Photos

Location Name: MAMM CREEK RANCH-67S92W/20NWSW

Location ID: 324054



**Photo 2.** Photo shows an overview of the southern/western portion of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801523

Inspection Photos

Location Name: MAMM CREEK RANCH-67S92W/20NWSW

Location ID: 324054



**Photo 3.** Photo shows an overview of the northern/eastern portion of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801523

Inspection Photos

Location Name: MAMM CREEK RANCH-67S92W/20NWSW

Location ID: 324054



**Photo 4.** Photo shows an example of reference area vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801523