

Inspection Photos

Location Name: TEP Rocky Mountain LLC RULISON DEEP 1 Pad

Location # 335269



Photo # 8191 From entrance to location



Photo # 8192 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC RULISON DEEP 1 Pad

Location # 335269



Photo # 8193 Location



Photo # 8194 Location



Inspection Photos

Location Name: TEP Rocky Mountain LLC RULISON DEEP 1 Pad

Location # 335269



May 19, 2023 at 9:27:10 AM
CO

Photo # 8195 Location



May 19, 2023 at 9:30:32 AM

Photo # 8198 Meter calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP Rocky Mountain LLC RULISON DEEP 1 Pad

Location # 335269



Photo # 8199 Meter calibration info not conspicuously posted



Photo # 8201 Containment liner needs maintenance

Inspection Photos

Location Name: TEP Rocky Mountain LLC RULISON DEEP 1 Pad

Location # 335269



Photo # 8202 Containment liner needs maintenance



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources