

Stormwater Management and Erosion control

Location Name: CAERUS PICEANCE LLC N PARACHUTE /WF08D-26H26A596.

Location #: 335642



Location Overview: A large stormwater event undercut the slide area and overran the access road and location #335642.

Section/Township/Range: 26 5S96W

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC N PARACHUTE /WF08D-26H26A596.
Location #: 335642



Northwest corner of location.



Northeast corner of location.



Southwest corner of location.



Southeast corner of location.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC N PARACHUTE /WF08D-26H26A596.
Location #: 335642



Photo #8 Mouth of channel entering location.



Photo #10 Tank battery.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC N PARACHUTE /WF08D-26H26A596.
Location #: 335642



Photo #21 Tank battery and mouth of channel.



Photo #22 Tank battery.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC N PARACHUTE /WF08D-26H26A596.
Location #: 335642



Photo #9995 Separator inundated with sediment.



Photo #17 Wellheads inundated with sediment.

Stormwater Management and Erosion control

Location Name: CAERUS PICEANCE LLC N PARACHUTE /WF08D-26H26A596.

Location #: 335642



Photo #16 Channel exit off location.



Photo #15 Channel exit off location.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC N PARACHUTE /WF08D-26H26A596.
Location #: 335642



Photo #12 Channel exit off location.



Photo #24 downstream of location.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC N PARACHUTE /WF08D-26H26A596.
Location #: 335642



Photo #28 Slide from location



Photo #29 Slide from location.

Stormwater Management and Erosion control

Access Road/Assoc. Location Name: CAERUS PICEANCE LLC N PARACHUTE /WF08D-26H26A596.

Access Road/Assoc. Location #: 335642



Access Road overview: The access road was overran. Caerus has reopened access to locations above the slide area.

Section/Township/Range: 26 5S96W

Stormwater Management and Erosion control

Access Road/Assoc. Location Name: CAERUS PICEANCE LLC N PARACHUTE /WF08D-26H26A596.

Access Road/Assoc. Location #: 335642



Photo #9991 Access road.



Photo # Access road and undercut slide area.

Stormwater Management and Erosion control

Access Road/Assoc. Location Name: CAERUS PICEANCE LLC N PARACHUTE /WF08D-26H26A596.

Access Road/Assoc. Location #: 335642



Photo #9991 Access road and undercut slide area



Photo # Access road and landslide flow channel.

Stormwater Management and Erosion control

Access Road/Assoc. Location Name: CAERUS PICEANCE LLC N PARACHUTE /WF08D-26H26A596.

Access Road/Assoc. Location #: 335642



Photo #9987 Flow channel of landslide.



Photo #9988 Flow channel of landslide.