

Inspection Photos

5/19/2023

Operator: SCOUT ENERGY MANAGEMENT LLC
- 10779

Location Number: 315463
Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location Number: 315463



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south. Vegetation observed on the Location is predominantly Undesirable Plant Species, such as Kochia, and Salsola sp.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location Number: 315463



Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location Number: 315463



Photo 3: Photo taken from southern reclamation areas, facing east. Photo shows vehicles have traveled over and re-disturbed the reclamation areas.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location Number: 315463



Photo 4: See comments under photo 3.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location Number: 315463



Photo 5: Photo example showing the surface of the reclamation areas. Desirable perennial plant germination/establishment on the Location was not observed; Location is bare or predominantly vegetated by Undesirable Plant Species such as Kochia, and Salsola sp.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location Number: 315463



Photo 6: Photo example showing vegetation over the adjacent reference are.