


WILLIFORD RESOURCES LLC - 96735

API# 05-067-06698 ANGELINA #4

Inspection Date : 5/18/2023



Pump jack with fence



FLIR Image of leaking wellhead
(See attached video file MOV_3554)