

WILLIFORD RESOURCES LLC - 96735
API# 05-067-06100 NETTIE #1
Inspection Date : 5/18/2023



Location overview looking S



Wellhead with pump jack.


WILLIFORD RESOURCES LLC - 96735

API# 05-067-06100 NETTIE #1

Inspection Date : 5/18/2023



Tank Battery



FLIR Image of leaking wellhead
(See attached video file MOV_3597)