

## Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 11-22 Pad

Location # 335181



Photo # 8289 From entrance to location



Photo # 8295 From entrance to location

# Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 11-22 Pad

Location # 335181



May 22, 2023 at 10:09:41 AM  
CO



May 22, 2023 at 10:13:37 AM  
CO

Photo # 8290 Location

Photo # 8294 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 11-22 Pad

Location # 335181



Photo # 8296 Location



Photo # 8306 Meter calibration info not conspicuously posted

## Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 11-22 Pad

Location # 335181



Photo # 8307 Meter calibration info not conspicuously posted

Photo # 8308 Meter calibration info not conspicuously posted

## Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 11-22 Pad

Location # 335181



**Photo # 8309 Meter calibration info not conspicuously posted**