

Inspection Photos

May 17, 2023

Operator: POC-I LLC - #10386

Location ID: 312752

Location Name: ILES DOME-64N92W/22SWSE

Inspection Document #: 702801531

Moffat County, CO

SWSE Section 22 T4N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ILES DOME-64N92W/22SWSE
Location ID: 312752



Photo 1. Photos taken from the location center show an overview to the north (left) and east (right).



Inspection Photos
Location Name: ILES DOME-64N92W/22SWSE
Location ID: 312752



Photo 2. Photos taken from the location center show an overview to the south (left) and west (right).

Inspection Photos
Location Name: ILES DOME-64N92W/22SWSE
Location ID: 312752



Photo 3. Photos show examples of equipment/debris found throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801531

Inspection Photos
Location Name: ILES DOME-64N92W/22SWSE
Location ID: 312752



Photo 4. Photos show examples of equipment/debris found throughout the location.



Inspection Photos
Location Name: ILES DOME-64N92W/22SWSE
Location ID: 312752



Photo 5. Photos show equipment/debris to the north of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801531

Inspection Photos
Location Name: ILES DOME-64N92W/22SWSE
Location ID: 312752



Photo 6. Photos show pipe debris which is present on location and also to the south (left) and north (right) of the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801531

Inspection Photos
Location Name: ILES DOME-64N92W/22SWSE
Location ID: 312752



Photo 7. Photo shows reference areas to the south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801531