

# Inspection Photos

May 17, 2023

Operator: POC-I LLC - #10386

Location ID: 312757

Location Name: ILES DOME UNIT-64N92W/23NENW

Inspection Document #: 702801535

Moffat County, CO

NENW Section 23 T4N R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: ILES DOME UNIT-64N92W/23NENW  
Location ID: 312757



**Photo 1.** Photos taken from the south shows an overview of the drive-through location. Note reclaimed areas to the right and slope insufficiently vegetated compared to reference to the left.





Inspection Photos  
Location Name: ILES DOME UNIT-64N92W/23NENW  
Location ID: 312757



**Photo 2.** Photos taken from the center of the location shows the slope to the west is insufficiently vegetated.





Inspection Photos

Location Name: ILES DOME UNIT-64N92W/23NENW

Location ID: 312757



5/17/23

+40.308197,-107.685072

23° NE

**Photo 3.** Photo shows insufficient vegetation on a portion of the location to the east.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801535




Inspection Photos  
Location Name: ILES DOME UNIT-64N92W/23NENW  
Location ID: 312757



**Photo 4.** Photos show examples of debris found throughout the location.



Inspection Photos  
Location Name: ILES DOME UNIT-64N92W/23NENW  
Location ID: 312757



**Photo 5.** Photos show examples of debris found throughout the location.





Inspection Photos  
Location Name: ILES DOME UNIT-64N92W/23NENW  
Location ID: 312757



**Photo 6.** Photos show examples of debris found throughout the location.



Inspection Photos  
Location Name: ILES DOME UNIT-64N92W/23NENW  
Location ID: 312757



**Photo 7.** Photos show examples of debris found throughout the location.