

## Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 120-27 Pad

Location # 324065



Photo # 8352 From entrance to location



Photo # 8354 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 120-27 Pad

Location # 324065

May 22, 2023 at 11:05:08 AM



Photo # 8355 Location

May 22, 2023 at 11:06:08 AM



Photo # 8356 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 120-27 Pad

Location # 324065



**Photo # 8357 Meter calibration info not conspicuously posted**



**Photo # 8358 Meter calibration info not conspicuously posted**