

Inspection Photos

Location Name: TEP Rocky Mountain LLC GV 25-27 Pad

Location # 311574



Photo # 8319 From entrance to location



Photo # 8320 From entrance to location

Inspection Photos
Location Name: TEP Rocky Mountain LLC GV 25-27 Pad
Location # 311574



Photo # 8321 Location



Photo # 8322 Location

Inspection Photos
Location Name: TEP Rocky Mountain LLC GV 25-27 Pad
Location # 311574



May 22, 2023 at 10:50:03 AM



May 22, 2023 at 10:44:13 AM

Photo # 8342 Location

Photo # 8327 Containment liner needs maintenance

Inspection Photos
Location Name: TEP Rocky Mountain LLC GV 25-27 Pad
Location # 311574



Photo # 8328 Containment liner needs maintenance



Photo # 8325 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP Rocky Mountain LLC GV 25-27 Pad

Location # 311574



Photo # 8326 Meter calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources