

Inspection Photos
Location Name: Randall Creek 29 PAD
Location ID: 444078



Photo 1 – Wellheads



Photo 2 – Wellhead

Inspection Photos
Location Name: Randall Creek 29 PAD
Location ID: 444078



Photo 3 – Tank Battery Signs



Photo 4 – Tank Battery

Inspection Photos
Location Name: Randall Creek 29 PAD
Location ID: 444078



Photo 5 – ECD



Photo 6 – Tank Battery

Inspection Photos
Location Name: Randall Creek 29 PAD
Location ID: 444078



Photo 7 – Separators and Heater Treaters



Photo 8 – Compressor

Inspection Photos
Location Name: Randall Creek 29 PAD
Location ID: 444078



Photo 9 – Wildlife Nettings are in disrepair



Photo 10 – Wildlife Nettings are in disrepair – Debris and Oily Waste

Inspection Photos
Location Name: Randall Creek 29 PAD
Location ID: 444078



Photo 11 – Wildlife Nettings are in disrepair – Debris and Oily Waste



Photo 12 –Injection Shed

Inspection Photos
Location Name: Randall Creek 29 PAD
Location ID: 444078



Photo 13 – Separators