

Inspection Photos

May 17, 2023

Operator: GRMR OIL & GAS LLC - #10524

Location ID: 312760

Location Name: DURHAM W T-64N90W/8SEnw

Inspection Document #: 702801539

Moffat County, CO

SEnw Section 8 T4N R90W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DURHAM W T-64N90W/8SEnw
Location ID: 312760



Photo 1. Photo taken from the southeast facing towards the location shows the unreclaimed access road.



Inspection Photos
Location Name: DURHAM W T-64N90W/8SEnw
Location ID: 312760



Photo 2. Photo taken from the location entrance shows an overview of the location. Note presence of remediation equipment.



Inspection Photos
Location Name: DURHAM W T-64N90W/8SEnw
Location ID: 312760



Photo 3. Photo shows cut slopes remain; recontouring/regrading is required.

Inspection Photos
Location Name: DURHAM W T-64N90W/8SEW
Location ID: 312760



Photo 4. Photo shows noxious weeds houndstongue and musk thistle.

