

LARAMIE ENERGY LLC, David/23-7 Pad

Location #334500



NW Corner of Location – Photo #03719



SW Corner of Location – Photo #03720

LARAMIE ENERGY LLC, David/23-7 Pad

Location #334500



NE Corner of Location – Photo #03721



SE Corner of Location – Photo #03722

LARAMIE ENERGY LLC, David/23-7 Pad

Location #334500



Separators – Photo #03727



Tank Battery – Photo #03728

LARAMIE ENERGY LLC, David/23-7 Pad

Location #334500



Location Lacks Stabilization – Photo #03723



Location Lacks Stabilization – Photo #03726

LARAMIE ENERGY LLC, David/23-7 Pad

Location #334500



Location Lacks Stabilization – Photo #03731



Location Lacks Stabilization – Photo #03732

LARAMIE ENERGY LLC, David/23-7 Pad

Location #334500



**Insufficient Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #03734**



**Insufficient Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #03735**