

Maralex Keegan Patrick 33-7-11 #1: Location ID/API #:067-08915



Photo #1 View of wellhead assembly and impacted material.

Maralex Keegan Patrick 33-7-11 #1: Location ID/API #:067-08915



Photo #2 View of missing bird protection cap.