

Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436710



Photo 1: Wellhead Sign



Photo 2: Bucket (trash) at pumpjack

Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436710



Photo 3: Wellhead Sign




Photo 4: Stained soil

Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436710



Photo 5: Wellhead sign



Photo 6: Stained soil

Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436710




Photo 7: Bucket (trash) at pumpjack



Photo 8: Tank Battery Sign

Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436710



Photo 9: Tank Battery



Photo 10: Equipment

Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436710



Photo 11: No current calibration