

Inspection Photos
Location Name: Diamond Valley East Pad
Location ID: 435083



Photo 1: Tank Battery Signs



Photo 2: Wellheads

Inspection Photos
Location Name: Diamond Valley East Pad
Location ID: 435083



Photo 3: Faded signage



Photo 4: No capacity/contents

Inspection Photos
Location Name: Diamond Valley East Pad
Location ID: 435083



Photo 5: Unused equipment



Photo 6: Unused equipment

Inspection Photos
Location Name: Diamond Valley East Pad
Location ID: 435083



Photo 7: Unused equipment



Photo 8: Unused signage

Inspection Photos
Location Name: Diamond Valley East Pad
Location ID: 435083




Photo 9: Not annually calibrated