

Inspection Photos

5/23/2023

Operator: CAERUS PICEANCE LLC - 10456

Location Number: 312399

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location Number: 312399



Photo 1: Photos taken from the north end of the Location, facing southeast and southwest. Photos provide an overview of the Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location Number: 312399



Photo 2: Photos 2-4 taken from the cut slopes of the Location. Photo shows slopes remain predominantly bare and exposed soils. Slopes lack stabilization and erosion degradation is evident.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location Number: 312399



Photo 3: Photo shows slopes remain predominantly bare and exposed soils. Slopes lack stabilization and erosion degradation is evident.

Inspection Photos

Name: CAERUS PICEANCE LLC - 10456

Location Number: 312399



May 23, 2023



May 23, 2023

Photo 4: Photo shows slopes remain predominantly bare and exposed soils. Slopes lack stabilization and erosion degradation is evident.