

Inspection Photos

5/23/2023

Operator: BLACK HILLS PLATEAU

PRODUCTION LLC - 10150

Location Number: 391225

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: BLACK HILLS PLATEAU PRODUCTION LLC - 10150

Location Number: 391225



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west. Photos show final reclamation of the Location, including compaction alleviation, recontouring/regrading and reclaiming, has not been performed beyond plugging the well. Surface Owner appears to be utilizing the site as a storage area. Note: Vegetation observed within photo is predominantly Undesirable and Noxious Plant species such as Whitetop.

Inspection Photos

Operator Name: BLACK HILLS PLATEAU PRODUCTION LLC - 10150

Location Number: 391225



Photo 2: See comments under photo 1. Arrow also shows what appears to be a soil stockpile on the southeast end of the Location.

Inspection Photos

Operator Name: BLACK HILLS PLATEAU PRODUCTION LLC - 10150

Location Number: 391225



Photo 3: Photo shows what appears to be the unlined pit on the Location has not been closed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: BLACK HILLS PLATEAU PRODUCTION LLC - 10150

Location Number: 391225



May 23, 2023



May 23, 2023

Photo 4: Photos examples showing vegetation on the Location. Vegetation observed on the Location is predominantly Undesirable and Noxious Plant species such as Whitetop. Photo right example of what appears to be Musk thistle rosettes; thistle rosettes observed throughout the Location.

Inspection Photos

Operator Name: BLACK HILLS PLATEAU PRODUCTION LLC - 10150

Location Number: 391225



Photo 5: Photos examples showing vegetation on the Location. Vegetation observed on the Location is predominantly Undesirable and Noxious Plant species such as Whitetop. Photo right example of what appears to be Musk thistle rosettes; thistle rosettes observed throughout the Location.

Inspection Photos

Operator Name: BLACK HILLS PLATEAU PRODUCTION LLC - 10150

Location Number: 391225



Photo 6: Photo shows what appears to be remaining pipe risers on the north end of the Location.