

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2023

Submitted Date:

05/24/2023

Document Number:

707601258

FIELD INSPECTION FORMLoc ID 445094 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445095	WELL	PR	03/01/2022	OW	123-42882	Shadow A26-646	WK

General Comment:

This is a WELL inspection.
Well(s): 1: Workover | WK.
WORKOVER OPERATIONS: Replace well tubing string.
Battery: Active.

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	YES		
Comment:	Controlling well with portable separator & combustor.		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 445095 Type: WELL API Number: 123-42882 Status: PR Insp. Status: WK**BradenHead**Date of Last Brhd Test: 03/26/2022 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: Date of last Brhd test > 1 yr.
Required reports not filed. Submit current Brhd test.
Submit reports per Rule 207.

Corrective Action: _____

Date: _____

Workover

Comment: Workover Contractor: Axis Energy Services, Rig #726.

Reference:
Form 42 on file. Notice of MIRU. Start Date: 05/22/2023. Approved.

2023/05/23:
Workover | WK
Workover Operations: Replace well tubing string.
Controlling well with portable separator & combustor.
2023/05/23: JSA attached as photo to this report.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 05/23/2023 at approximately 14:16 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: Shadow/A26-651 Pad Location ID: 445094 Well Name(s): Shadow A26-646. API: 123-42882. Location County: Weld County, Colorado Weather: Mostly Sunny w/ haze, damp areas from prior storm.</p> <p>While there, I observed: Well(s): 1: Workover WK. WORKOVER OPERATIONS: Replace well tubing string. Battery: Active.</p> <p>WELL STATUS COMMENT: Workover WK. Replace well tubing string. Workover WK well GPS coordinates: 40.456450 / -104.476440</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/24/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601259	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6124736