

# Inspection Photos

API: 043-06219

Operator: AUSCO PETROLEUM INC

Inspection Date: 5/22/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 5/22/2023

## Inspection Photos



**Photo 1.** Facing northwest along the access road. There are some check dams where stormwater is going around the check dam. BMP maintenance is needed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 5/22/2023

## Inspection Photos



**Photo 2.** Facing northwest along the access road. There are some check dams where stormwater is going around the check dam. BMP maintenance is needed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 5/22/2023

## Inspection Photos



**Photo 3.** Facing north toward the location. Interim reclamation has been performed and the location is reduced in size.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 5/22/2023

## Inspection Photos



**Photo 4.** There was some desirable vegetation beginning to establish in the reclamation area but there is a lot of undesirable weeds (Russian thistle) that will need to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 5/22/2023

## Inspection Photos



**Photo 5.** Facing north toward the location. There are displaced wattles that need to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 5/22/2023

## Inspection Photos



**Photo 6.** The sediment trap at the west side of the location has filled in with sediment and needs to be cleaned out. There are also noxious weeds (Canada thistle) that need to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 5/22/2023

## Inspection Photos



**Photo 7.** Facing northeast toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 5/22/2023