

TEP  
MDP 2  
Location # 414794



Previous inspection photo from document #  
708900567



Follow up photo of new valve on Braden head

**TEP  
MDP 2  
Location # 414794**



**Previous inspection photo from document #  
708900567**



**Follow up photo of chemical tank containment still  
full of fluid.**

**TEP  
MDP 2  
Location # 414794**



**Previous inspection photo from document #  
708900567**



**Follow up photo of chemical tank containment still  
full of fluid.**