

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 22-2 Pad

Location ID: 323962



May 24, 2023 at 11:58:40 AM
CO



May 24, 2023 at 11:59:19 AM
CO

Photo # 8520 From entrance to location

Photo # 8521 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 22-2 Pad

Location ID: 323962



May 24, 2023 at 11:59:46 AM
CO



May 24, 2023 at 12:03:07 PM
CO

Photo # 8522 Location

Photo # 8523 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 22-2 Pad

Location ID: 323962



Photo # 8525 Unmarked deadman



Photo # 8530 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 22-2 Pad

Location ID: 323962



Photo # 8535 Meter calibration info not conspicuously posted



Photo # 8536 Meter calibration info not conspicuously posted