

Inspection Photos
Location Name: Dawson A 1
API: 05-061-06023



1. Dawson A 1 pumping unit in the background. There's a roll of wire (from an old REDA pump) hanging on the REA pole north of the wellhead

Insp #701007013 performed in accordance with Complaint Doc #403326184