

Inspection Photos

API: 061-06010

Operator: WESTERN OPERATING COMPANY

Inspection Date: 5/15/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06010 - Date: 5/15/2023

Inspection Photos



Photo 1. Drone aerial photo facing northwest from the Foster #1 wellsite. There are multiple impacted areas from previous spill. Site investigation and remediation will need to occur.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06010 - Date: 5/15/2023

Inspection Photos



Photo 2. Drone aerial photo facing northwest from the Foster #1 wellsite. There is multiple impacted areas from previous spill. Site investigation and remediation will need to occur.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06010 - Date: 5/15/2023

Inspection Photos



Photo 3. Drone aerial photo facing back southeast toward the Foster #1 wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06010 - Date: 5/15/2023

Inspection Photos



Photo 4. Facing toward the tank battery site. The tanks have been removed and there is an electric wire fence around the area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06010 - Date: 5/15/2023

Inspection Photos



Photo 5. Facing toward the Foster #1 wellsite which is in process to be plugged and abandoned.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06010 - Date: 5/15/2023

Inspection Photos



Photo 6. Facing toward the tank battery site. The tanks have been removed and there is an electric wire fence around the area. All pipe risers and equipment will need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06010 - Date: 5/15/2023