

Inspection Photos

API: 071-06399

Operator: OGRIS OPERATING LLC

Inspection Date: 5/24/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 5/24/2023

Inspection Photos



Photo 1. Facing northwest toward the [GE-73-94](#) location standing across the canyon.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 5/24/2023

Inspection Photos



Photo 2. There are old noxious weeds in this area that may have been treated last year and no re-germination was observed. Lat/Long:37.155134,-104.90373. This area could use additional hand seeding to establish more vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 5/24/2023

Inspection Photos



Photo 3. Facing south at the reclaimed location. The vegetation has not fully established at the location and additional hand seeding should be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 5/24/2023

Inspection Photos



Photo 4. Facing northwest at the reclaimed location. The vegetation has not fully established at the location and additional hand seeding should be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 5/24/2023