

Inspection Photos
Location Name: Lari 12-33
Location ID: 310705



Photo 1 – Pumping Unit




Photo 2 – Wellhead – Stained Soil