

**Inspection Photos**  
**Location Name: Fabrizius 33-14**  
**Location ID: 413933**



**Photo 1 – Wellhead**



**Photo 2 – Wellhead Sign**

**Inspection Photos**  
**Location Name: Fabrizius 33-14**  
**Location ID: 413933**



**Photo 3 – Pumping Unit**




**Photo 4 – Stained Soil at Exhaust**



**Inspection Photos**  
**Location Name: Fabrizius 33-14**  
**Location ID: 413933**



**Photo 5 – Stained Soil at Gas Engine**



**Photo 6 – Stained Soil at Gas Engine**

**Inspection Photos**  
**Location Name: Fabrizius 33-14**  
**Location ID: 413933**



**Photo 7 – Stained Soil at Wellhead**