

Inspection Photos  
Location Name: Wilson PC GQ 2-4  
Location ID: 417766



Photo 1 – Wellhead

Photo 2 – Pumping Unit

**Inspection Photos**  
**Location Name: Wilson PC GQ 2-4**  
**Location ID: 417766**



**Photo 3 – Stained Soil**

**Photo 4 – Oily Waste**