

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC GM 267-3 Pad
Location ID: 324120



Photo # 8743 From entrance to Location

Photo # 8744 From entrance to Location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC GM 267-3 Pad
Location ID: 324120



Photo # 8745 Location



Photo # 8746 Location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC GM 267-3 Pad
Location ID: 324120



Photo # 8747 Location



Photo # 8749 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 267-3 Pad

Location ID: 324120



Photo # 8750 Meter calibration info not conspicuously posted



Photo # 8751 Meter calibration info not conspicuously posted