

LARAMIE ENERGY LLC, Buzzard Creek/14B Pad

Location #334555



NE Corner of Location – Photo #03915



NW Corner of Location – Photo #03916

LARAMIE ENERGY LLC, Buzzard Creek/14B Pad

Location #334555



SW Corner of Location – Photo #03917



SE Corner of Location – Photo #03918

LARAMIE ENERGY LLC, Buzzard Creek/14B Pad

Location #334555



Wellheads – Photo #03919



Separators – Photo #03922

LARAMIE ENERGY LLC, Buzzard Creek/14B Pad

Location #334555



Tank Battery – Photo #03923



Location Lacks Stabilization – Photo #03925

LARAMIE ENERGY LLC, Buzzard Creek/14B Pad

Location #334555



Location Lacks Stabilization – Photo #03928

Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03929

LARAMIE ENERGY LLC, Buzzard Creek/14B Pad

Location #334555



**Insufficient Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #03930**