

FORM
43

Rev
05/21

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

02/24/2023

Document Number:

403330435

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 17320 Contact Person: Emma Millar
Company Name: CITY & COUNTY OF DENVER Phone: (208) 610-6012
Address: 8500 PENA BLVD AOB 10TH FLOOR Fax: ()
City: DENVER State: CO Zip: 80249-6340 Email: emillar@cottonwoodconsulting.com

Identification Information

API Number: 05 - 001-06732 OGCC Facility ID: 201329 Initial Form 19 or 27 Document number: 403147779
Facility Name: BOX ELDER J Facility Number: 1 Facility Type: WELL
Location QtrQtr: NWSW Section: 32 Township: 1S Range: 65W Meridian:
County: ADAMS Field Name: WATTENBERG
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: CITY & COUNTY OF DENVER Agent Name: Emma Millar Title: Consultant
Phone Number: 208-610-6012 Email: emillar@cottonwoodconsulting.com

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 201329 Facility Name: BOX ELDER J 1 Facility Type: Oil and Gas Well
Location: QtrQtr: NWSW Sec: 32 Twp: 1S Range: 65W Meridian: 6
County Name: ADAMS Latitude: 39.918770 Longitude: -104.693460

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 107934 Document Name: Size of file in bytes: 32117 File Name: Box Elder J #1 Soil Sample EDD (9).xlsx
Sample Type: Matrix:
Facility ID: 201329 Sample ID: 646430 Sample Name: Box Elder J#1 Sample Date: 01/06/2023
Collection Point: Soil Matrix: SOIL Pre Post: Remediation
Project Number: Remediation Number: 25218 Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2301063-01

Batch ID: 107930	Document Name: Size of file in bytes: 32384	File Name: Box Elder J #1 Soil Sample EDD (7).xlsx
SampleType: _____		Matrix: _____
Facility ID: 201329	Sample ID: 646426	Sample Name: Box Elder J#1
Collection Point: PRODEQP	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: 25218	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
		Lab Sample ID: 2210059-07
Batch ID: 107931	Document Name: Size of file in bytes: 32401	File Name: Box Elder J #1 Soil Sample EDD (8).xlsx
SampleType: _____		Matrix: _____
Facility ID: 201329	Sample ID: 646427	Sample Name: Box Elder J#1
Collection Point: PRODEQP	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: 25218	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
		Lab Sample ID: 2210059-08
Batch ID: 107926	Document Name: Size of file in bytes: 32404	File Name: Box Elder J #1 Soil Sample EDD (3).xlsx
SampleType: _____		Matrix: _____
Facility ID: 201329	Sample ID: 646422	Sample Name: Box Elder J#1
Collection Point: SEP	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: 25218	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
		Lab Sample ID: 2210059-03
Batch ID: 107924	Document Name: Size of file in bytes: 32426	File Name: Box Elder J #1 Soil Sample EDD (1).xlsx
SampleType: _____		Matrix: _____
Facility ID: 201329	Sample ID: 646420	Sample Name: Box Elder J#1
Collection Point: PRODEQP	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: 25218	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
		Lab Sample ID: 2210059-01
Batch ID: 107927	Document Name: Size of file in bytes: 32397	File Name: Box Elder J #1 Soil Sample EDD (4).xlsx
SampleType: _____		Matrix: _____
Facility ID: 201329	Sample ID: 646423	Sample Name: Box Elder J#1
Collection Point: PRODEQP	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: 25218	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
		Lab Sample ID: 2210059-04
Batch ID: 107925	Document Name: Size of file in bytes: 32378	File Name: Box Elder J #1 Soil Sample EDD (2).xlsx
SampleType: _____		Matrix: _____
Facility ID: 201329	Sample ID: 646421	Sample Name: Box Elder J#1
Collection Point: PRODEQP	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: 25218	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
		Lab Sample ID: 2210059-02

Batch ID: 107928 Document Name: Size of file in bytes: 32402 File Name: Box Elder J #1 Soil Sample EDD (5).xlsx

SampleType: Matrix:

Facility ID: 201329 Sample ID: 646424 Sample Name: Box Elder J#1 Sample Date: 10/05/2022

Collection Point: PRODEQP Matrix: SOIL Pre Post: Remediation

Project Number: Remediation Number: 25218 Complaint Number: NOAV Number:

Inspection Number: Spill Number: Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2210059-05

Batch ID: 107929 Document Name: Size of file in bytes: 32349 File Name: Box Elder J #1 Soil Sample EDD (6).xlsx

SampleType: Matrix:

Facility ID: 201329 Sample ID: 646425 Sample Name: Box Elder J#1 Sample Date: 10/05/2022

Collection Point: PRODEQP Matrix: SOIL Pre Post: Remediation

Project Number: Remediation Number: 25218 Complaint Number: NOAV Number:

Inspection Number: Spill Number: Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2210059-06

Batch ID: 107935 Document Name: Size of file in bytes: 32563 File Name: Box Elder J #1 Soil Sample EDD (10).xlsx

SampleType: Matrix:

Facility ID: 201329 Sample ID: 646431 Sample Name: Box Elder J#1 Sample Date: 01/23/2023

Collection Point: WellHead Matrix: SOIL Pre Post: Remediation

Project Number: Remediation Number: 25218 Complaint Number: NOAV Number:

Inspection Number: Spill Number: Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2301164-01

Sample Facility Attachment:

No Facility Attachment

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	The data submitted by the operator can be accessed through the COGIS data system.	05/29/2023

Total: 1 comment(s)